


ANACONDA Copper Company

New Mexico Operations
P.O. Box 638
Grants, New Mexico 87020
505/876-2211



March 25, 1980

Mr. A. F. Czarnowsky
Area Mining Supervisor
UNITED STATES DEPARTMENT OF INTERIOR
GEOLOGICAL SURVEY
P.O. Box 26124
Albuquerque, New Mexico 87125

Re: Jackpile Mine Reclamation Plan
Report - Fourth Quarter, 1979.

Dear Mr. Czarnowsky:

In accordance with the Jackpile Mine Reclamation Plan, we submit the following data for the Fourth Quarter of 1979:

1. Radiological Analysis of Ground and Surface Water.
2. Chemical Analysis of Ground and Surface Water.
3. Results of the Air Monitoring Program.
4. Results of the Ambient Radon Study.

Sincerely,

MEADE A. STIRLAND

Manager, Environmental Health & Safety

MAS/jms
Encls.